



The State of Utah

Department of
Natural Resources

Division of
Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:

Company	Jay Marshall	Resident Agent
OGM	Karl Houskeeper	Environmental Scientist III

Inspection Report

Permit Number:	C0070013
Inspection Type:	COMPLETE
Inspection Date:	Monday, May 10, 2004
Start Date/Time:	05/10/2004 10:00:00 AM
End Date/Time:	05/10/2004 2:00:00 PM
Last Inspection:	Thursday, March 25, 2004

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear/Windy, ~Temp 78 Deg F

InspectionID Report Number: 261

Accepted by: pgrubaug
06/01/2004

Permittee: **UTAHAMERICAN ENERGY INC**

Operator: **UTAHAMERICAN ENERGY INC**

Site: **HORSE CANYON MINE**

Address: **PO BOX 986, PRICE UT 84501**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

6,032.07	Total Permitted
122.49	Total Disturbed
61.65	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
- ☒ State
- ☒ County
- ☒ Fee
- ☐ Other

Types of Operations

- ☒ Underground
- ☐ Surface
- ☒ Loadout
- ☐ Processing
- ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permitting actions: Permit application for Lila Canyon is under review by the Division.

Inspector's Signature: _____

Date Monday, May 10, 2004

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

Permit Number: C0070013
 Inspection Type: COMPLETE
 Inspection Date: Monday, May 10, 2004

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
 - a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
 - b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit expires 05/06/2006. Other documents include the following:

- Certificate of Insurance terminates 06/01/2004.
- UPDES permit UTG040013 expires midnight 04/30/2008, (Horse Canyon Mine).
- UPDES permit UTG040024 expires midnight 04/30/2008, (Lila Canyon Mine).
- Air Quality Permit DAQE-702-99.

The status of the mine site is Phase II Bond Release. The inspection frequency for this mine site is quarterly.

2. Signs and Markers

Checked the ID sign at the public accesses to the facilities area. The ID signs give the phone number of the new resident agent. The other signs and markers viewed meet the coal rules.

4.a Hydrologic Balance: Diversions

Work on the diversion channel west of the old refuse pile site is scheduled to begin this week. This item was identified during the midterm review.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The silt fence and small erosional channel by the reclaimed sediment pond are scheduled for repair this week. The sediment quarterly inspection was done on March 31, 2004. This inspection was P.E. certified on April 22, 2004. No problems were noted.

4.c Hydrologic Balance: Other Sediment Control Measures

The silt fences by the diversion west of the old refuse pile, by the reclaimed sediment pond, and at the water storage tank are scheduled for repair this week.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2003 water monitoring information is in the EDI website and uploaded. First quarter 2004 water monitoring information has been collected and the information still needs to be placed in the EDI website. Water samples for second quarter 2004 water monitoring were collected during the inspection.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for March 2004. No discharge took place from any of the outfalls.

19. AVS Check

An AVS check was done on May 10, 2004 and compared to the information submitted in the PMLU application. The information from the AVS check matches the information in the PMLU application. There were no violations retrieved by the AVS system check.

20. Air Quality Permit

Air quality permit DAQE-702-99 was issued on August 27, 1999 and remains in effect.

21. Bonding and Insurance

Bond number SUR004892 for \$1,137,726 was increased to \$1,253,000 on January 24, 2001. Phase II Bond Release was approved on February 12, 2003, which dropped the bond by \$191,672. The current bond is now \$1,061,328. The bond is through Lincoln General Insurance Co. This Bond is for Part A (Horse Canyon).

Bond number SB9905586 is for Part B (Lila Canyon Extension). The Bond amount is \$1,556,000 from XL Specialty Insurance. The Lila Canyon Extension has been submitted to the Division and is currently under review.

Insurance is through Federal Insurance Company policy # 37104410. The insurance was issued on 06/01/2003 and expires on 06/01/2004. Explosive coverage is noted. The minimum coverage is met and the certificate holder is listed as the State of Utah, Division of Oil, Gas and Mining. The operator was made aware of the expiration date.